

Permanent Magnetic Lifter Repair & Recalibration Service

In accordance with ASME B30 standards, DocMagnet is pleased to announce the launch of a new reconditioning/recertification service for ALL MAKES of magnetic lifters up to 5000LB SWL capacity.

Under the current standard, all close-proximity lifting magnets must undergo periodic inspection which should include recertification by a qualified professional.

A qualified DocMagnet Technician will undergo a series of checks and where necessary, rework to bring the unit back to standard.

The inspection/rework includes the following:

1. **Pole Shoes:** Check for flatness and parallelism. Remove all burrs.
2. **Lever Mechanism:** Check for smoothness of operation. Check locking assembly and proper functionality.
3. **Hoist Ring:** Check for excessive wear.
4. **Labels:** Check for legibility of SWL and critical warnings. Replace if necessary.
5. **Pull Tests:** Undertake a series of pull tests.
6. **Flux Tests:** Undertake a series of Flux Density tests to check raw magnet performance.
7. **Issuance of a Certificate of Conformity.**




Popular brands covered by this service:

- DocMagnet
- Tecnomagnete
- Alpha
- Chinese Imports
- And more. Call to find out if your lifter can be tested.

Additional services include:

- 24 hour return service
- Temporary loan facility
- Part-Exchange deals



DocMagnet



A 3-year materials and labor warranty, as well as a performance guarantee, is offered with these products.